## TECHNICAL INFO **HONDA**

O Type of vehicle

Honda Civic, (06-12), 1,8l, 103kw (140 hp), year of construction 2006-2012

O Vehicles in question

All models.

## PROBLEM

The ABS warning light, the brake system warning light and the handbrake warning light illuminate when starting the engine.

O Cause of the problem.

There might be error codes saved.

When starting the engine there is a low battery voltage.

O Fault elimination

It is recommended to read out the error codes and if necessary to rectify the malfunction.

Besides that you should charge or replace the battery.

O Type of vehicle

Honda Civic, (06-12), 1,8l, 103kw (140 hp), year of construction 2006-2012

O Vehicles in question

All models produced between 2005 and 2008.

## PROBLEM

Brake shudders, coming from the front wheels.

O Cause of the problem

The front brake discs could have an excessive lateral run-out.

O Fault elimination

It is recommended to check the lateral run-out of the front brake discs.

If necessary the brake disc has to be replaced.

O Type of vehicle

Honda Civic / CR-V

O Vehicles in question
Honda Civic MY 2006-2007
Honda CR-V MY 2007

PROBLEM

Error code saved: U0122.

Besides that, there might be error codes saved concerning the CAN bus.

O Cause of the problem

A bad ground connection of the ABS control unit is present.

**O** Error elimination

It is recommended to check the state of the ground point.

[Honda Civic: behind the front bumper; CR-V: underneath the ABS control unit.] If necessary, it is recommended to clean or tighten the ground point. Read out the error codes and, if necessary, correct the malfunction.

