

TECHNICAL INFO

CHRYSLER

○ Type of vehicle

Chrysler Voyager, (TYP GK/GY/RG), 3,3l V6, 128kw (174 hp), year of construction 2001-2008

○ Vehicles in question

All models with all-wheel drive.

● PROBLEM

Driving slowly without brake activation there is a noise coming from the rear brakes occurring.

○ Cause of the problem

The brake caliper carrier of the rear brake is faulty.

○ Fault elimination

It is recommended to install an amended brake caliper carrier for the rear brake.