

TECHNICAL INFO

AUDI

○ Type of vehicle

Audi Q7, 3,6l, BHL, 206kW (280 hp) at 6200 rpm, R-Cat, year of construction 2007-2010

○ Vehicles in question

All models of the construction years 2006-2009.

● PROBLEM

The warning light of the parking brake doesn't switch off after releasing the parking brake.

○ Cause of the problem

The lever of the parking brake, which is actuated via footswitch, doesn't return in its original position, due to a too weak design.

○ Fault elimination

It is recommended to install a new gas spring at the lever of the footswitch.