

# TECHNICAL INFO

## AUDI

### ○ Type of vehicle

Audi Q7, 3,6l, BHL, 206kW (280 hp), year of construction 2007-2010

### ○ Vehicles in question

All models of the construction years 2006-2009

### ● PROBLEM

The warning light of the parking brake doesn't switch off after releasing the parking brake.

### ○ Cause of the problem

The lever of the parking brake doesn't return in its original position, due to a too weak design.

### ○ Fault elimination

It is recommended to install a new gas spring at the lever of the footswitch.