


09.A604.10/.11 SUPERSEDED BY 09.B338.21

The references **09.A604.10/.11** are replaced by **09.B338.21** by modifying the internal side hub.

The **OES BMW** corresponding to the new Brembo reference are:

3421 6 764 653, 3421 6 864 901, 3421 6 855 008, 3421 6 855 657


09.A604.10/.11



Breco references:
BS 8802 / BV 8802

AP references:
25192 / 25192 V

09.B338.21



Breco reference:
BV 8926

AP reference:
25316 V